

McNary Dam Unit Operating Priority 2008

Existing 2007 Priority: 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14

Recommended 2008 Priority: 1, 2, 3, 14, 13, 12, 11, 10, 9, 8, 7, 6, 5, 4
(units 1-3, then switch to northern units, moving north to south).

Reason for Change: The recommended change will improve tailrace egress with operation of the TSWs while maintaining adequate water velocity at the juvenile bypass outfall.